

Annexure D

BUILDING SAFETY CERTIFICATE

पत्रांक..... 508

दिनांक. 13/05/24

एकांकित संख्या..... 9.01

कार्यालय अधिशासी अभियन्ता
निर्माण खण्ड लो.नि.वि. लोहाघाट

No.

It is certified that the existing building **Mallikarjun School** (name of the building or premises) at **Chiryadunga ,Banigaoun,Lohaghat** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Floors(3) Wings (2)					

The building is owned/occupied by **Mallikarjun School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD** (Name of Department/ Govt.) on 15.05.2024 (date of inspection) in the presence of Mr. Rahul Singh Dev (9897048021) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 16.05.24 for a period of Two years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on Dt. 16.05.2024 at **Lohaghat** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature] 16/05/24

Name : Santay Chaurhan

Designation : Executive Engineer

Name & Address of Department/ Office: C.D. P.W.D.

Lohaghat

66 | Page

Er. Deepak Datta (PWE)

उपरोक्त अर्थ में निरीक्षण कर लोहाघाट में निर्माण कार्य के उपरान्त विद्यालय अथवा अन्य संस्थाओं को सौंप दिया गया है।

13-5-24

सहायक अभियन्ता
निर्माण खण्ड लो.नि.वि.
लोहाघाट